



- 41. Were discharges observed at the authorized outfalls?
- 42. Were any unauthorized discharges observed?
- 43. Number and location of discharge points are as described in permit?
- 44. Locations adequate for representative samples?
- 45. Is this facility required to have a storm water P2 plan?

**MISCELLANEOUS**

- |   | Yes                                 | No                                  | N/A                      |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 46. Is there a Water Appropriation permit for the site?       | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 47. Is the wetland and waterway crossing(s) being maintained? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

**PHOTOS**



**Figure 1: Google Earth™ Aerial Photo.**



**Figure 6:** Site view from Cherry Hill Road.



**Figure 7:** Haul road, berms, and drainage.



**Figure 8:** Site overview facing East.



**Figure 3:** LOD from FDA Blvd.